



2913 N. Ontario St., Burbank, CA 91504
 818-446-2450 www.bmwburbank.com
 BAR#283757 EPA ID#CAL000417063

Repair Order Invoice

Doc Number: 43643
 Service Writer: LEE HANES
 Date Printed: 02/26/2019
 Date Promised: 07/24/2018
 Date In: 07/24/2018
 Cashier: JUSTIN GRAY
 Cashier Date: 07/25/2018

PINHAS BARAK

~~X5216 HARTSDALE ST~~
~~SHERMAN OAKS, CA 91403~~

Customer Information

Home Phone: 818-398-3989
 Work Phone: 818-398-3989
 Email: PINIBARAK@MARBLESERVIC

Fold Here

Unit 2018 12/18/12 K1600gtl

Color:white

Keyboard:

VIN/SerialWB10F1208JZD91283

Plate:

Odom/Hrs16,669

Out:16,672

K1600GT/L 18K SERVICE

Description:IF A VALVE ADJUSTMENT IS REQUIRED IT WILL REQUIRE AN ADDITIONAL 1.9 HOURS AND THE COST OF SHIMS.

CUSTOMER ALSO STATED TO ME OVER PHONE THERE WAS A LOSS OF THROTTLE BUT HAVE NOT BEEN ABLE TO DUPLICATE HAS MULTIPLE AFTERMARKET GAGETRY ALL OVER VEHICLE THAT ARE NONE OEM PLEASE SEE ATTACHED PHOTOS FOR REFERENCE WITH OUT ALL OF THESE ITEMS REMOVED AND BIKE RETURNED TO STOCK ANY FURTHER CONCERNS WITH THROTTLE CAN NOT BE PROPERLY DIAGNOSED WITH A COMPROMISED SYSTEM COULD NOT DUPLICATE ANY CONCERN OF THROTTLE INOP

Resolution:PERFORMED 18 K SERVICE AS REQUESTED BY CUSTOMER

CHANGED OIL AND FILTER
 CHECKED VALVE CLEARANCES NO ADJUSTMENT NEED ALL VALVES WITHIN FACTOR SPEC. MEASUREMENTS WERE SHOWN TO THE CUSTOMER
 REPLACE SPARK PLUGS CHECK CLUTCH SYSTEM
 INSPECT COMPLETE BRAKE SYSTEM
 REAR PADS GOOD @ 80%
 FRONT PADS GOOD @ 75%
 CHECKED ALL ELECTRICAL
 CHECKED LIGHTING ALL FUNCTIONS
 RESET SERVICE LIGHT
 LUBED SIDE AND CENTER STAND
 CHECKED COOLANT AND COOLING SYSTEM
 CHECKED TIRE TREAD 75% FRONT 70% REAR
 TIRE FRONT PSI 36
 REAR TIRE 42 PSI
 BIKE IS A GOOD REPRESENTATION OF A BMW PRODUCT
 THANK YOU FOR YOUR BUSINESS
 BMW OF BURBANK !!!

Recommend:ADVISE CHECK COOLANT WITH IN 1000 MILES

Part #	Qty	Description	Price	Discount	Total
11427673541	1.00	Oil filter	\$19.45	\$0.00	\$19.45
07119963252	1.00	Gasket ring	\$1.78	\$0.00	\$1.78
12127728657	6.00	LMAR8AI-8 SPARK PLUG	\$26.83	\$0.00	\$160.98
82142209769	1.00	Antifreeze/Coolant - Quart	\$8.00	\$0.00	\$8.00

Part #	Qty	Description	Price	Discount	Total
11127728760	1.00	Gasket set, cylinder head co	\$131.19	\$0.00	\$131.19
11127674654	12.00	Rubber bush	\$3.50	\$0.00	\$42.00
83212365959	5.00	MOTOR OIL ADVANTEC 5W-40	\$16.50	\$0.00	\$82.50
Parts Subtotal					\$445.90

Description	Technician	Hour	Total
18K SERVICE	MARCOS VARGAS	4	\$440.00
Labor Subtotal			\$440.00

Job Subtotal **\$885.90**

All Jobs Subtotal: **\$885.90**

Los Angeles County 9.5% - 9.50%: **\$42.36**

Total: **\$928.26**

Less Deposits: **\$0.00**

Visa/Mastercard: **(\$928.26)**

Total Due: **\$0.00**

Bike has multiple cameras ,front and rear, has multiple sets of led lighting as well as various chargers ,radar detectors all non oem
CUSTOMER WAS ADVISED THAT THIS COULD BECOME A 2 DAY SERVICE AND WAS OK WITH THIS
HE WAS ALSO QUOTED NEW COST FOR CHANGE IN SERVICE

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OR WARRANTIES: Any warranties on the products sold hereby are those made by the manufactures. The seller here expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

Any motorcycle not picked up after 3 business days from the date of notification of completion will be assessed a storage fee of \$75 per day.

Motorcycles for repair will be stored outside during normal business hours. If you do not want your motorcycle exposed to the outside elements you are required to provide a cover for your motorcycle.

I hereby acknowledge that I was notified & gave oral approval of the above estimate: I hereby acknowledge receiving estimate of repairs:

Signature: _____

**BMW MOTORCYCLES
OF BURBANK**

