



2913 N. Ontario St., Burbank, CA 91504
 818-446-2450 www.bmwburbank.com
 BAR#283757 EPA ID#CAL000417063

Repair Order Invoice

Doc Number: 43202
 Service Writer: LEE HANES
 Date Printed: 02/27/2019
 Date Promised: 05/09/2018
 Date In: 05/09/2018
 Cashier: LEE HANES
 Cashier Date: 07/28/2018

DANIEL MORDECAI HAFT

~~5754 BIANCA AVE~~
~~ENCINO, CA 91436~~

Customer Information

Home Phone: 818-705-4430
 Cell Phone: 818-400-4707
 Email: DHAFT@SBCGLOBAL.NET

Fold Here

Summary

Unit	Job	Job Total
2018 BMW K1600GTL	CUSTOMER STATES BIKE HAS THROTTLE CONCERN CHECK AND ADVISE	WARRANTY

Job Subtotal:	<u>\$0.00</u>
Total:	<u>\$0.00</u>
Less Deposits:	<u>\$0.00</u>
Total Due:	<u>\$0.00</u>

SENT 5-22 LH
 SENT TO ANNETE ON 6-30 LH
 SENT AGAIN 7-25 LH

TERMS: STRICTLY CASH UNLESS ARRANGEMENTS ARE MADE. "I hereby authorize the repair work hereinafter to be done along with the necessary material and agree that you are not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond your control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto."

DISCLAIMER OR WARRANTIES: Any warranties on the products sold hereby are those made by the manufactures. The seller here expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose, and the seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products. Any limitation contained herein does not apply where prohibited by law.

Any motorcycle not picked up after 3 business days from the date of notification of completion will be assessed a storage fee of \$75 per day.

Motorcycles for repair will be stored outside during normal business hours. If you do not want your motorcycle exposed to the outside elements you are required to provide a cover for your motorcycle.

I hereby acknowledge that I was notified & gave oral approval of the above estimate: I hereby acknowledge receiving estimate of repairs:

Signature: _____

Detail

Unit 2018 BMW K1600GTL

Color: LIGHT WHITE

Keyboard:

VIN/Serial WB10F1202JZD91280

Plate:

Odom/Hrs 3,988

Out: 4,001

1146 - CUSTOMER STATES BIKE HAS THROTTLE CONCERN CHECK AND ADVISE

Description: CUSTOMER STATES IS PERIODIC BUT UPON START UP BIKE IDLES UP TO 3000 RPM AND WILL NOT COME DOWN AND BIKE DOES NOT SHIFT OR REV UP OR DOWN UNTIL POWER IS CUT OFF AND TURNED BACK ON

Resolution: DOES NOT CURRENTLY HAVE ENGINE LIGHT ON OR LOSS OF THROTTLE INPUT. CONNECTED TO ISTA WORKSHOP, FAULT FOUND 3A1421 "THROTTLE VALVE 1", FREQUENCY 1. ACCORDING TO PUMA MEASURE US 63473054-03 TOLERANCES FOR THROTTLE VALVE AND THROTTLE GRIP SENSORS FOR I LEVELS PRIOR TO K001-17-11-501 CAN CAUSE FALSE FAULT FOR EITHER SENSOR, I LEVEL OF BIKE IS K001-17-03-501, REQUIRES UPDATING. PERFORMED PROGRAMMING, UPDATED I LEVEL TO K001-18-03-501, SEE FINAL REPORT. TEST RODE, NO PROBLEMS NOTED.

Description	Technician	Hour	Total
DIAGNOSIS	COLE LEVERTON	WARRANTY	WARRANTY
1361522/3 6100002/3 = 6 NOT 5	COLE LEVERTON	WARRANTY	WARRANTY
Labor Subtotal			WARRANTY

Job Subtotal WARRANTY

All Jobs Subtotal: \$0.00

Total: \$0.00

Less Deposits: \$0.00

Total Due: \$0.00

